

ROAD TRAFFIC SIGN SURVEY

SEPTEMBER 2018

Speed sign has been hit but it is clean

DIRTY



Oncoming vehicles in middle of road

Misleading -

No visible narrowing of road here - unnecessary  
black plastic traffic calming posts. Dirty & unnecessary



LARKS GATE

30MPH sign unnecessary when Village Gates are erected




DIRTY ROAD MARKINGS -  
SLOW WITHIN 50 YARDS  
IS THIS NECESSARY?

Multiple messages



Black and white posts good condition.

Village boundary is Sheepwash Bridge





SHEEPWASH BRIDGE

Road markings are faded, but see introductory comments.

**POUND MEADOW**

Wooden Posts – what purpose do these serve? In good condition.



on either side of entrance to Pound Meadow




**PIGEON LANE JUNCTION**



Speed sign obscured by branches, otherwise clean and in good condition

adjacent to Lursi's Cottage



Sign  
in  
middle  
of  
footpath




Signs obscured by branches  
& telegraph post

Traffic calming bollards, two broken all  
dirty



FORGE END





3a

4



b)



a)

a) and b) - signs in ok condition  
some obstruction from tree branches

b) 'oncoming vehicles' sign in middle  
of footpath. as observed already,  
the message is false.





Speed sign faded but serviceable.  
Signage proliferation on the nearside  
approaching mini-roundabout.

(b)



30 mph sign dwarfed and unnecessary right after traffic calming area.

Width of footpath at this section is impassable for push-chair or mobility scooter without mounting grass verge.

Message on information board obscured by telegraph pole.



See comments on (6) about obstruction of footpath. This section is like a slalom for pedestrians / mobility scooter users. There is a barrage of information for the motorist, on both sides of the road.



8



Directional sign not properly secured.



Sign - 6 traffic messages within a dozen yards.



a)



b)

- a) Entering the village from Bury
- b) Exiting the village towards Bury  
Speed sign partly obscured by hedge
- a) Speed camera sign on outside  
obscured by hedge (see § 10a)





a)



Approaching mini-roundabout

- a) Playground sign on newside obscured by hedge. (See 10 a)). Bus stop sign also obscured.













Heading towards  
Mere Lane



a)



b)

Note the Give Way sign is twisted  
In the wrong direction

- a) We do not have speed cameras; a recurrent issue on other stretches of road. See introductory comments.
- b) Highways need to re-position sign.

# Tutt Hill

13

30

Neighbourhood Watch faded. No use whatsoever

30

3 more at the very top

4 betwixt Alpa and next house



Obscured by branches

Half reflection bollards 6 betwixt Green Riding and next house. All dirty good condition but serving no real purpose

1 Broken. Dirty, shabby unnecessary

Bollards on wrong side of the road for driver's vision. Distraction rather than warning. 7 in total before Pond house. 5 split or smashed

Not true Obscured by branches



Broken are these necessary?

13a)

30

Tutt Hill sign frame & supports in need of attention - very shabby

13b)





(13) a) b)



13 b)



a)



Broken posts



Mistleading and part obscured sign





Painted Neighbourhood  
Watch sign

Obscured and misleading  
traffic calming sign



a)



b)



a) & b) - obscured signage

c) Superfluous speed sign